

Gear Machine - Ratio chart for: BZ222

Internal ratio: 2.1

	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91
12	13.125	13.300	13.475	13.650	13.825	14.000	14.175	14.350	14.525	14.700	14.875	15.050	15.225	15.400	15.575	15.750	15.925
13	12.115	12.277	12.438	12.600	12.762	12.923	13.085	13.246	13.408	13.569	13.731	13.892	14.054	14.215	14.377	14.538	14.700
14	11.250	11.400	11.550	11.700	11.850	12.000	12.150	12.300	12.450	12.600	12.750	12.900	13.050	13.200	13.350	13.500	13.650
15	10.500	10.640	10.780	10.920	11.060	11.200	11.340	11.480	11.620	11.760	11.900	12.040	12.180	12.320	12.460	12.600	12.740
16	9.844	9.975	10.106	10.238	10.369	10.500	10.631	10.763	10.894	11.025	11.156	11.288	11.419	11.550	11.681	11.813	11.944
17	9.265	9.388	9.512	9.635	9.759	9.882	10.006	10.129	10.253	10.376	10.500	10.624	10.747	10.871	10.994	11.118	11.241
18	8.750	8.867	8.983	9.100	9.217	9.333	9.450	9.567	9.683	9.800	9.917	10.033	10.150	10.267	10.383	10.500	10.617
19	8.289	8.400	8.511	8.621	8.732	8.842	8.953	9.063	9.174	9.284	9.395	9.505	9.616	9.726	9.837	9.947	10.058
20	7.875	7.980	8.085	8.190	8.295	8.400	8.505	8.610	8.715	8.820	8.925	9.030	9.135	9.240	9.345	9.450	9.555
21	7.500	7.600	7.700	7.800	7.900	8.000	8.100	8.200	8.300	8.400	8.500	8.600	8.700	8.800	8.900	9.000	9.100
22	7.159	7.255	7.350	7.445	7.541	7.636	7.732	7.827	7.923	8.018	8.114	8.209	8.305	8.400	8.495	8.591	8.686
23	6.848	6.939	7.030	7.122	7.213	7.304	7.396	7.487	7.578	7.670	7.761	7.852	7.943	8.035	8.126	8.217	8.309
24	6.563	6.650	6.738	6.825	6.913	7.000	7.088	7.175	7.263	7.350	7.438	7.525	7.613	7.700	7.788	7.875	7.963
25	6.300	6.384	6.468	6.552	6.636	6.720	6.804	6.888	6.972	7.056	7.140	7.224	7.308	7.392	7.476	7.560	7.644
26	6.058	6.138	6.219	6.300	6.381	6.462	6.542	6.623	6.704	6.785	6.865	6.946	7.027	7.108	7.188	7.269	7.350
27	5.833	5.911	5.989	6.067	6.144	6.222	6.300	6.378	6.456	6.533	6.611	6.689	6.767	6.844	6.922	7.000	7.078
28	5.625	5.700	5.775	5.850	5.925	6.000	6.075	6.150	6.225	6.300	6.375	6.450	6.525	6.600	6.675	6.750	6.825
29	5.431	5.503	5.576	5.648	5.721	5.793	5.866	5.938	6.010	6.083	6.155	6.228	6.300	6.372	6.445	6.517	6.590
30	5.250	5.320	5.390	5.460	5.530	5.600	5.670	5.740	5.810	5.880	5.950	6.020	6.090	6.160	6.230	6.300	6.370
31	5.081	5.148	5.216	5.284	5.352	5.419	5.487	5.555	5.623	5.690	5.758	5.826	5.894	5.961	6.029	6.097	6.165
32	4.922	4.988	5.053	5.119	5.184	5.250	5.316	5.381	5.447	5.513	5.578	5.644	5.709	5.775	5.841	5.906	5.972
33	4.773	4.836	4.900	4.964	5.027	5.091	5.155	5.218	5.282	5.345	5.409	5.473	5.536	5.600	5.664	5.727	5.791
34	4.632	4.694	4.756	4.818	4.879	4.941	5.003	5.065	5.126	5.188	5.250	5.312	5.374	5.435	5.497	5.559	5.621
35	4.500	4.560	4.620	4.680	4.740	4.800	4.860	4.920	4.980	5.040	5.100	5.160	5.220	5.280	5.340	5.400	5.460
36	4.375	4.433	4.492	4.550	4.608	4.667	4.725	4.783	4.842	4.900	4.958	5.017	5.075	5.133	5.192	5.250	5.308
37	4.257	4.314	4.370	4.427	4.484	4.541	4.597	4.654	4.711	4.768	4.824	4.881	4.938	4.995	5.051	5.108	5.165
38	4.145	4.200	4.255	4.311	4.366	4.421	4.476	4.532	4.587	4.642	4.697	4.753	4.808	4.863	4.918	4.974	5.029
39	4.038	4.092	4.146	4.200	4.254	4.308	4.362	4.415	4.469	4.523	4.577	4.631	4.685	4.738	4.792	4.846	4.900
40	3.938	3.990	4.043	4.095	4.148	4.200	4.253	4.305	4.358	4.410	4.463	4.515	4.568	4.620	4.673	4.725	4.778

<http://www.gearmachine.net/>