

How to fix poor fit of servo horns on the Corona Servo CS238MG






Press the horn over the shaft
with the tape



The Teflon has formed nicely over
the shaft and filled up the splines





After tightening the screw, the horn fits very nicely on the splined shaft without any play